

## U.S. Environmental Protection Agend

## Superfund (CERCLIS)

EPA Home > Envirofacts > CERCLIS > Query Results





## **Query Results**





Site ID: Equal To: OHD980611388

Results are based on data extracted on MAY-08-2003

Note: Click on the underlined CORPORATE LINK value for links to that company's environmental web pages.

Click on the underlined MAPPING INFO value to obtain mapping information for the facility.

Click on the underlined RECORD OF DECISION value for a RODS Site Report.

Click on the underlined "View Facility Information" link to view EPA Facility information for the facility.

Go To Bottom Of The Page

**CERCLIS EPA ID:** OHD980611388

STREET ADDRESS: CITY NAME:

STATE ABBR:

ZIP CODE:

**COUNTY NAME:** 

CORPORATE

LINK:

LATITUDE:

LONGITUDE:

SITE SMSA:

1976 SPRINGBORO

ROAD

MORAINE

OH 45439

MONTGOMERY

No

2000

SITE NAME:

**FACILITY INFORMATION** 

OWNERSHIP STATUS:

FEDERAL FACILITY:

**NPL STATUS:** 

SITE INCIDENT TYPE:

RECORD OF DECISION

(ROD) INFO:

**EPA REGIONAL** 

LINK:

**MAPPING INFO:** 

SOUTH DAYTON DUMP

& LANDFILL

View facility information

Other

Not on the NPL

No

No

MAP

**Enforcement and Cleanup Actions** 

Action	Action ID	Planned Start Date	Planned End Date	Actual Start Date	Actual End Date	Responsibility	Planned Outcome	Urgency
NEGOTIATION (GENERIC)	001			09/26/2002	01/10/2003	Federal Enforcement		
EXPANDED SITE INSPECTION	001			02/08/1996	01/25/1997	State, Fund Financed	Recommended for HRS Scoring	
SITE INSPECTION	001		No. of the contract of the con		08/06/1991	EPA Fund-Financed	High	
PRELIMINARY ASSESSMENT	001				06/28/1985	EPA Fund-Financed	Low	
DISCOVERY	001				06/01/1981	EPA Fund-Financed		

## **Site Description**

There were no Site Descriptions reported for this site.

Go To Top Of The Page

Total Number of Facilities Displayed: 1

EPA Home | Privacy and Security Notice | Contact Us

Last updated on Monday, May 19th, 2003 http://oaspub.epa.gov/enviro/cerclis\_web.report